

# CLASSIFICATION REPORT INTERTEK TESTING SERVICES NA INC.

5541 Central Ave. Suite 110

Boulder, CO 80301 USA

Job No. 3133403

Issued: 10/26/07  
Page 1 of 21  
Revised: 10/22/08

REPORT NO. 3133403DEN-001

INSPECTION, TESTS AND EVALUATION  
OF AN  
X-RAY COLLIMATOR

RENDERED TO

COLLIMARE LLC  
ARVADA, CO

**GENERAL:** This Report gives the results of the inspection, tests and evaluation of an X-Ray Collimator for compliance with the Standards listed below, with regard to the risks of fire and shock only. This investigation was authorized by Purchase Order No. C1025 dated 09/11/07. The investigation was begun on 10/09/2007 and completed on 10/31/2007. A prototype sample in good condition was provided by the client on 10/08/2007 and tested at the local Intertek Office located at 5541 Central Ave, Suite 110, Boulder, CO 80301 USA.

Standard for Safety UL 60601-1 Medical Electrical Equipment, Part 1: General Requirements for Safety First Edition, Dated April 25, 2003 including revisions through April 26, 2006

Standard for Safety IEC 60825-1

Safety of laser products - Part 1: Equipment classification and requirements Second Edition, dated 01/03/2007

**Applicant:** Collimare, LLC  
13406 W 60th Ave  
Arvada, CO, 80004  
USA

**Contact:** Mr. Howard Thomas  
**Phone:** 303-955-3091  
**Fax:** 303-955-3092

**Manufacturer:** Collimare, LLC.  
12150 W 44th Ave. Unit 202  
Wheat Ridge, CO 80033  
USA

**Contact:** Mr. Howard Thomas  
**Phone:** 303-955-3091  
**Fax:** 303-955-3092

**An independent organization testing for safety, performance, and certification.**

This report is for the exclusive use of Intertek's Client and is provided pursuant to the agreement between Intertek and its Client. Intertek's responsibility and liability are limited to the terms and conditions of the agreement. Intertek assumes no liability to any party, other than to the Client in accordance with the agreement, for any loss, expense or damage occasioned by the use of this report. Only the Client is authorized to permit copying or distribution of this report and then only in its entirety. Any use of the Intertek name or one of its marks for the sale or advertisement of the tested material, product or service must first be approved in writing by Intertek. The observations and test results in this report are relevant only to the sample tested. This report by itself does not imply that the material, product, or service is or has ever been under an Intertek certification program.